

TO BE FILLED BY THE INSPECTING OFFICER

ASSISTANT ENGINEER

1. Name of the Officer : ASHOK KUMAR RUDRA
2. Name of the School : AMRITA VIDYALAYAM
3. Location with Name of District / Sub District : 24 SOUTH PARAGANAS
4. Classification of Building and Size : RCC ROOF WORK
Old Bldg. : 7.45x5.88x3.2 -10 NOS(GF), 7.45x5.88x3.2 -9 NOS(FF), 7.45x5.88x3.2 -9 NOS(SF)
Extn. Bldg. : 7.45x7.00x3.35 - 13 NOS(GF), 7.45x7.00x3.35 - 12 NOS(FF), 7.45x7.00x3.35 - 12 NOS(SF),
7.45x7.00x3.35 - 12 NOS(TF)
Total: 76 nos

5. Period which Certificate Issued : 2017 ONWARDS

6. Nature of Defect if any : NIL
a. Foundation : NIL
b. Super Structure : NIL
c. Doors & Windows : NIL
d. Wood work wrought and put up : NIL
e. Roof : NIL
f. Flooring : NIL
g. Miscellaneous : NIL

7. Any major defects notices which will
render the building unsafe in any manner : NIL

8. Whether maintenance work
have been done properly: YES

9. Whether structure is sound enough
or not for conducting classes: SOUND ENOUGH FOR CONDUCTING CLASSES

Note: The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood, etc.

Any additional observation deemed necessary for the certificate may be furnished separately with the certificate. Certificate that school was inspected by me on Date: 20.06.2021 and found fit to conduct classes for the period for the reason stated above.

Name:

Date:

Signature:

A.K. Rudra 23.06.2021
ASHOK KUMAR RUDRA
BCE - MIE
Chartered Civil Engineer
Regd. No -0/041668
233, Lake Gardens, Kolkata-700 045

Asstt. Eng
24/6/2021
Sub-Asstt. Engineer
Building Section
Maheshtala Municipality

Chairperson
Chairperson
Board of Administrators
Maheshtala Municipality
24 JUN 2021